



Construction Update – September 2018



CONSTRUCTION PROGRESS

Construction Complete:

- G19 prototype display apartment
- Roof installation
- Bulk hot water installation
- Glazing installation
- Project crane dismantle
- Electrical and plumbing rough in
- Ground, Level 1 and Level 2 plastering
- Communal courtyard window shroud installation

Construction in progress:

- Basement fit out
 - Balcony balustrade installation
 - Ground and Level 1 – kitchen & bathroom joinery installation
 - Ground and Level 1 – bathroom tiling
 - Pergola structure installation
 - Communal courtyard and terrace planter boxes
-

Late Jan to Early Feb 2019

Late-February 2019

Anticipated Construction Completion

Anticipated Apartment Settlements

Next construction update – November 2018

PEIYEE KONG 0499 770 383
PROJECTS@CASURBAN.COM.AU

